CORNER RECORD

COUNTY OF MADERA T. 11 S R. 18 E M.D.B.&M. MERIDIAN CALIFORNIA

CORNER TYPE: GOV'T. CORNER [✓] MEANDER [ ] RANCHO [ ] CONTROL [ ] OTHER [ ]

CORNER IDENTIFICATION — DATE OF VISIT January 1976



W¼ Corner, Section 28

CORNER — LEFT AS FOUND [ ] FOUND AND TAGGED [✓] REESTABLISHED OBLITERATED CORNER [ ] REBUILT [ ]

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

3/4" Iron Pipe Found and Tagged R.C.E. 16,995

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST [ ] SECOND [ ] THIRD [ ]

STATIONS USED: NGS (USC & GS) [ ] STATE [ ] COUNTY [ ] OTHER [ ] STATION _____ STATION _____

ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (Include reference tie or witness points, remarks and topo of area)



SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON January 17 1976.

SIGNED: Lawrence R. Martin

Licensed R.C.E. No.: 16,995

SEAL

REGISTERED PROFESSIONAL ENGINEER LAWRENCE R. MARTIN No. 16,995 CIVIL STATE OF CALIFORNIA

COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED April 6 1976

AND EXAMINED AND FILED 4-15 1976

BY: A. Costa

TITLE: County Engineer

DOCUMENT No. 76-09-1

STATEMENT ON BACK OF SHEET YES [ ] NO [✓]