


CORNER RECORD

Document Number \_\_\_\_\_

City or \_\_\_\_\_ County of Madera, California

Legal Description Lot 63 of Lake Madera Country Estates  
per Book 10 of Maps at Page 85, M.C.R.



CORNER TYPE

COORDINATES  
(Optional)

Government Corner  Control   
Meander  Property   
Rancho  Other   
Date of Survey \_\_\_\_\_

N. \_\_\_\_\_  
E. \_\_\_\_\_  
Zone \_\_\_\_\_ Datum \_\_\_\_\_  
Elev. \_\_\_\_\_

Corner — Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:  
Found original monuments at SW & SE CORNERS, NO I.D.  
SET TAG IN SW MONUMENT, REPLACED SE WITH 3/4" x 29"  
I.P.

A description of the physical condition of the monument as found and as set or reset: \_\_\_\_\_

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with  
the Land Surveyors' Act on October 7, 2003  
Signed Douglas A. Bredahl L.S. Number 4509



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 10/15/03 and examined  
and filed 10/17/03  
Signed David M. McGlasson Title ACTING CO. SURVEYOR




County Surveyor's Comment \_\_\_\_\_

NORTH



1" = 100'

NOTE: FOUND ORIGINAL 1" X 22" I.P. (NO I.D.) S82°47'14"E 0.67' FROM RECORD POSITION. MARK CHADWICK (OWNER LOT 64) TOLD ME HIS CONTRACTOR REPLACED THIS MONUMENT AFTER IT WAS DISTURBED DURING RETAINING WALL CONSTRUCTION.



- MONUMENTS FOUND & ACCEPTED, 1" X 22" I.P.S (ORIGINAL) ID GONE, AS NOTED
- MONUMENTS SET, 3/4" X 29" TAGGED L.S. 4509 AS NOTED