

CORNER RECORD


Document Number _____

City of _____

County of Madera California

Brief Legal Description NE Cor. Sec. 3, T. 10 S., R. 22 E., M.D.M.

CORNER TYPE



Government Corner Control

Meander Property

Rancho Other

Date of Survey
March 13, 2002

COORDINATES (optional)

N. 1859112.1

E. 6838367.6

Epoch 1998.5

NAD83

Zone 3

Corner: Left as Found Established Reestablished Rebuilt Remon. Amended

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

NE Cor. Sec. 3, T. 10 S., R. 22 E., M.D.M.

A description of the physical condition of the monument as found and as set or reset.

GLO mon, 3 ins. diam., with brass cap, firmly set, projecting 6 ins., above the ground. Added the date 2002 to the cap and added new reference objects along with remaining original bearing tree.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on Feb. 12 2004
Signed Ronald McNamee L.S. or R.C.E Number _____

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received Feb 13 2004 and examined and filed Feb 18 2004
Signed David McGlasson Title ACTING CO. SURVEYOR




County Surveyor's Comment

Refer to Bureau of Land Management, California State Office, Official Survey, Group 1357, T. 10 S., R. 22 E., Mount Diablo Meridian, March 13, 2002, Volume R 606, Page 38-39.



A PK NAIL AND SHINER
ON TOP OF A GRANITE OUTCROP AT S END
9' X 5' X 2'

A PK NAIL AND SHINER
ON TOP OF A GRANITE OUTCROP
8' X 8' X 3 1/2'



S.73°14'E.
150.7

A PK NAIL AND SHINER
ON TOP OF A GRANITE OUTCROP
8' X 8' X 2'

A PK NAIL AND SHINER
ON TOP OF A GRANITE BOULDER
3' X 3' X 2'