


CORNER RECORD

Document Number _____

City of _____

County of MADERA, California

Brief Legal Description NORTHWEST CORNER SECTION 25, T. 10 S., R. 17 E.,
MOUNT DIABLO BASE AND MERIDIAN



CORNER TYPE

Government Corner Control
 Meander Property
 Rancho Other
 Date of Survey OCTOBER 4, 2001

COORDINATES(Optional)

N. _____
 E. _____
 Zone NAD27 NAD83
 NAD83 Epoch _____
 Elevation _____
 Vert. Datum: NGVD29 NGV88
 Meas. Units: Metric Imperial

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
FOUND 2" BRASS CAP FLUSH IN PAVEMENT, STAMPED RCE 14155 PER CORNER RECORD NO. 76-28-12

A description of physical condition of the monument as found and as set or reset:

FOUND 2" BRASS CAP FLUSH IN PAVEMENT, STAMPED RCE 14155 IN GOOD CONDITION.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on OCTOBER 5, 2001.

Signed _____ P.L.S. or R.C.E Number 5277



COUNTY SURVEYOR'S STATEMENT


This corner record was received OCT 8, 2001 and examined and filed OCT 12, 2001.

Signed M.T. Kim P.L.S. or R.C.E Number 7609

Title County Surveyor

County Surveyor's Comment _____





1017600301