


Document Number _____

City of _____

County of Madera, California

Brief Legal Description North Quarter Corner, Section 5, T. 12 S., R. 18 E., M.D.B. & M., Avenue 12 and Road 28 1/2.



CORNER TYPE

Government Corner Control
 Meander Property
 Rancho Other

Date of Survey 6-30-2000

COORDINATES(Optional)

N. _____
 E. _____
 Zone _____ NAD27 NAD83
 NAD83 Epoch _____
 Elevation _____
 Vert. Datum: NGVD29 NAV88
 Meas. Units: Metric Imperial

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

Found concrete nail, with 2' ties North & West. Tied-out prior to road construction.

Monument was reestablished from ties set prior to road construction.


A description of the physical condition of the monument as found and as set or reset: _____

Monument was destroyed. Set 2" brass cap in 1.20' x 1.20' concrete, flush. See monument stamp.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on July 11, 2000.

Signed [Signature] P.L.S. or R.C.E. Number P.L.S. 6335




COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 7/27, 2000 and examined and filed 7/31, 2000.

Signed David M. McBlairson P.L.S. or R.C.E. Number 6968

Title ACTING CO. SURVEYOR

County Surveyor's Comment _____





NORTH QUARTER CORNER SECTION 5, T. 12 S., R. 18 E., M.D.B. AND M.
Avenue 12

TIES:

- 181.89' NORTHEAST TO A NAIL AND SHINER IN POWER POLE.
- 180.43' SOUTHEAST TO CHISELED "X" ON TOP OF CURB, WEST END CURB & GUTTER.
- 333.89' NORTHWEST TO NAIL AND SHINER IN POWER POLE.
- 97.90' NORTHWEST TO NAIL AND SHINER IN POWER POLE.

MONUMENT STAMP:



1218240700