CORNER RECORD

COUNTY OF Madera T. 13S R. 17 E MERIDIAN CALIFORNIA

CORNER TYPE: GOV'T. CORNER ☐ MEANDER ☐ RANCHO ☐ CONTROL ☒ OTHER ☐

CORNER IDENTIFICATION — DATE OF VISIT October 11, 19 75



Northwest corner, Section 17
T 13 S, R 17 E

CORNER — LEFT AS FOUND ☐ FOUND AND TAGGED ☒ REESTABLISHED OBLITERATED CORNER ☐ REBUILT ☐

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

2" Iron Pipe

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

2" Iron Pipe Tagged 23,841

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST ☐ SECOND ☐ THIRD ☐

STATIONS USED: NGS (USC & GS) ☐ STATE ☐ COUNTY ☐ OTHER ☐ STATION _____ STATION _____

ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (Include reference tie or witness points, remarks and topo of area)



SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON Nov 3 19 75.

SIGNED: Jack M. Gilbert

L.S. or R.C.E. No.: RCE 23,841

SEAL

COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED 11-3 19 75

AND EXAMINED AND FILED 11-3 19 75

A. Brote BY. County Engineer

TITLE: _____

DOCUMENT No. 75-38-05

STATEMENT ON BACK OF SHEET

YES ☐ NO ☐