


CORNER RECORD

COUNTY OF MADERA TOWNSHIP 11 SOUTH, RANGE 13 EAST; M.D.B.&M. CALIFORNIA

CORNER TYPE: GOV'T. CORNER MEANDER RANCHO CONTROL OTHER

CORNER IDENTIFICATION - DATE OF VISIT: _____ 19____



NORTHWEST CORNER SECTION 2 11/13

CORNER - LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

3 x 3 REDWOOD DOWN 8" (OXALIS & JERROLD AVES.)

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD

STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____ STATION _____

ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (INCLUDE REFERENCE TIE OR WITNESS POINTS, REMARKS AND TOPO OF AREA)

TIES:

SOUTHEAST	232.10'	⊙ ON POWER POLE KV
SOUTHWEST	110.70'	⊙ ON METER POLE
SOUTHWEST	115.20'	⊙ ON POWER POLE
SOUTHWEST	128.50'	⊙ ON POWER POLE KV
SOUTH	20.20'	POWER LINE WEST

COPIED FROM FRESNO COUNTY TIES

SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYOR'S ACT ON _____ 19____.

SIGNED: _____

L.S. or R.C.E. No: _____

SEAL

COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED _____ 19____

AND EXAMINED AND FILED _____ 19____.

BY: _____

TITLE: _____

DOCUMENT No: _____

STATEMENT ON BACK OF SHEET: YES NO